



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	319	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5726		Ranny	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 24

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0024.JPG

Image Status: Image found and displayed.



Photo No: 25

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0025.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 319

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\319.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	5711	Street Prefix:		Street Name:	Chilham	Street Type:	ROAD
Source Type:	01= Main Sewer	Location:	8=Yard-Back	Severity:	3=Moderate		
Sector:	1=Public	Drainage Area:	150				
Comments:	hole in ground						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_A\A_2004_1027Image0015.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5713		Chilham	ROAD

Source Type:	02= Service Line	Location:	8=Yard-Back	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	150		

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_A\A_2004_1027Image0016.JPG

Image Status: Image found and displayed.



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID320-A2\2005_0519Image008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	5713	Street Prefix:		Street Name:	Chilham	Street Type:	ROAD
Source Type:	02= Service Line	Location:	2=Paved Asphalt	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	150				
Comments:	hole in ground						

SMOKE TEST PHOTOS



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_A\A_2004_1027Image0017.JPG

Image Status: Image found and displayed.



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID320-A2\2005_0519Image008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5703		Chilham	ROAD

Source Type:	02= Service Line	Location:	8=Yard-Back	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	45		

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 26

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0026.JPG

Image Status: Image found and displayed.



Photo No: 27

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0027.JPG

Image Status: Image found and displayed.



Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID320-B1_2005_0519Image009.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5701		Chilham	ROAD

Source Type:	02= Service Line	Location:	8=Yard-Back	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	400		

Comments:

SMOKE TEST PHOTOS



Photo No: 28

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0028.JPG

Image Status: Image found and displayed.



Photo No: 29

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0029.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID320-B2_2005_0519Image010.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5707		Chilham	ROAD

Source Type:	01= Main Sewer	Location:	8=Yard-Back	Severity:	4=Major
Sector:	1=Public	Drainage Area:	1000		

Comments:

SMOKE TEST PHOTOS



Photo No: 30

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0030.JPG

Image Status: Image found and displayed.



Photo No: 31

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0031.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5717		Uffington	ROAD

Source Type:	02= Service Line	Location:	8=Yard-Back	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	600		

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 32

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0032.JPG

Image Status: Image found and displayed.



Photo No: 33

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0033.JPG

Image Status: Image found and displayed.



Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID320-B4\2005_0519Image007.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2119		Sulgrave	AVE

Source Type:	01= Main Sewer	Location:	7=Yard-Front	Severity:	4=Major
Sector:	1=Public	Drainage Area:	250		

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 34

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0034.JPG

Image Status: Image found and displayed.



Photo No: 35

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0035.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	320	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2117		Sulgrave	AVE

Source Type:	05= Downspout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	600		

Comments:

SMOKE TEST PHOTOS




Photo No: 36

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0036.JPG

Image Status: Image found and displayed.



Photo No: 37

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0037.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 320

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\320.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5726		Uffington	ROAD

Source Type:	02= Service Line	Location:	9=Yard-Side	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	100		

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_A\A_2004_1027Image0018.JPG

Image Status: Image found and displayed.



Photo No: 1

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID321-A1_2005_0519Image001.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2110		Webb	LANE

Source Type:	01= Main Sewer	Location:	11=Field	Severity:	4=Major
Sector:	1=Public	Drainage Area:	1550		

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No: 38

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0038.JPG

Image Status: Image found and displayed.




Photo No: 41

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0041.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2110		Webb	LANE

Source Type:	01= Main Sewer	Location:	11=Field	Severity:	4=Major
Sector:	1=Public	Drainage Area:	5000		

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No: 39

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0039.JPG

Image Status: Image found and displayed.



Photo No: 41

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0041.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2110		Webb	LANE

Source Type:	01= Main Sewer	Location:	8=Yard-Back	Severity:	3=Moderate
Sector:	1=Public	Drainage Area:	2300		

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No: 40

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0040.JPG

Image Status: Image found and displayed.



Photo No: 41

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0041.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:		
2110		Webb	LANE		
Source Type:	01= Main Sewer	Location:	11=Field	Severity:	2=Trace
Sector:	1=Public	Drainage Area:	2800		
Comments:	near unmapped MH				

SMOKE TEST PHOTOS



Photo No: 42

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0042.JPG

Image Status: Image found and displayed.



Photo No: 43

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0043.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2106		Uffington	ROAD

Source Type:	02= Service Line	Location:	11=Field	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	1350		

Comments: hole in ground / not clear if this is a public or private defect

SMOKE TEST PHOTOS




Photo No: 44

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0044.JPG

Image Status: Image found and displayed.



Photo No: 45

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0045.JPG

Image Status: Image found and displayed.



Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID321-B5_2005_0519Image002.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2106		Uffington	ROAD

Source Type:	02= Service Line	Location:	11=Field	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	1000		

Comments: hole in ground / not clear if this is a public or private defect

SMOKE TEST PHOTOS



Photo No: 46

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0046.JPG

Image Status: Image found and displayed.



Photo No: 45

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0045.JPG

Image Status: Image found and displayed.



Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID321-B5_2005_0519Image002.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	321	Date:	10/27/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2106		Uffington	ROAD

Source Type:	02= Service Line	Location:	8=Yard-Back	Severity:	4=Major
Sector:	2=Private	Drainage Area:	1725		

Comments: hole in ground / not clear if this is a public or private defect

SMOKE TEST PHOTOS



Photo No: 47

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0047.JPG

Image Status: Image found and displayed.



Photo No: 48

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0048.JPG

Image Status: Image found and displayed.



Photo No: 49

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1027-2004\T-1\PLAYER_B\B_2004_1027Image0049.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 321

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\321.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	322	Date:	10/28/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	Y
Defect No:	1	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5618		Newbury	St

Source Type:	14= Catch Basin	Location:	1=Paved Concrete	Severity:	4=Major
Sector:	1=Public	Drainage Area:	7500		

Comments: hole in ground / not clear if this is a public or private defect

SMOKE TEST PHOTOS



Photo No: 1

Filename Path:
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1028-2004\T-1\PLAYER_A\A_2004_1028Image0001.JPG

Image Status: Image found and displayed.



Photo No: 2

Filename Path:
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1028-2004\T-1\PLAYER_A\A_2004_1028Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 322

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\322.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	322	Date:	10/28/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5618		Newbury	St

Source Type:	18= Other	Location:	1=Paved Concrete	Severity:	3=Moderate
Sector:	1=Public	Drainage Area:	500		

Comments:

SMOKE TEST PHOTOS



Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1028-2004\T-1\PLAYER_A\A_2004_1028Image0002.JPG

Image Status: Image found and displayed.



Photo No: 3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1028-2004\T-1\PLAYER_A\A_2004_1028Image0003.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 322

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\322.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.